To be filled by the Inspecting Officer (Asst.Engineer)
(Re.GO Ms 20/70/PWD Dt; 23-01-1970)

1. 2. 3. 4.	Name of Officer Name of School Location with name of Education District/Sub District Classification of building s as specified in column4 of the application for fitness certificate and size		AMAL-K. SAJERY Dawn Public School Pallerethi, Emakula 53.50×12.20×3.65 (inc 51.50×6.20×3.65 21.90×6.20×3.65 11.50×6.20×3.65
5.	Period for which the certificate is issued	:	2022-23
6.	Nature of defeets, if any,	:	<u> </u>
	a). Foundation and basement	:	
	b). Superstructure	:	all
	c) Doors and Windows	:	
	d) Wood work wrought and put up	:	(
	e) Roof	:	
	f) Flooring)
	g) Miscellaneous (crack etc)	:	NIL
7	Any major defects noticed which will render		
	the building unsafe in any manner	•	NIL
8.	Whether maintenance work have been		
	done properly	•	Yes,
9.	Whether the structure is sound or not for		1
	conducting Classes.	:	Sound under Normal
	Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of ward exposure of flood etc. 2. Any additional observation if deemed necessary for the certificate may be forwarded separately with this certificate.		

CERTIFICATE

Certified that the School building was inspected by me on 28 104 12 and found to stated above.

Place: Pallinuth,
Date: 28/04/222

Assistant Engineer

PALLURUTHY ZONAL OFFICE KOCHI MUNICIPAL CORPORTION