


FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst.Engineer)
(Re.GO Ms 20/70/PWD Dt: 23-01-1970)

1. Name of Officer : SASIKALA . P . R
2. Name of School : THE DAWN PUBLIC SCHOOL
3. Location with name of Education District/Sub District : PALLURUTHY , ERNAKULAM
4. Classification of buildings as specified in column 4 : RCC BUILDING (THREE FL
of the application for fitness certificate and size
G/F - 53.50 x 12.20 x 3.65
F/F - 51.50 x 6.20 x 3.65
S/F - 21.90 x 6.20 x 3.65
" - 11.50 x 6.20 x 3.65
5. Period for which the certificate is issued : 2024 - 2025
6. Nature of defects , if any, :
 - a). Foundation and basement : NIL
 - b). Superstructure : NIL
 - c). Doors and Windows : NIL
 - d). Wood work wrought and put up : NIL
 - e). Roof : NIL
 - f). Flooring : NIL
 - g). Miscellaneous (crack etc) : NIL
7. Any major defects noticed which will render the building unsafe in any manner : NIL
8. Whether maintenance work have been done properly : Yes
9. Whether the structure is sound or not for conducting Classes. : Yes, Sound under normal weather conditions


JASSIYA. S
PRINCIPAL
THE DAWN PUBLIC SCHOOL
P. Gangadharan Road, Marunnukada
Palluruthy, Kochi - 682 006, Kerala


ADAM OOSMAN
MANAGER
THE DAWN PUBLIC SCHOOL
PALLURUTHY
KOCHI - 682006


Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of ward exposure of flood etc. 2. Any additional observation if deemed necessary for the certificate may be forwarded separately with this certificate.

CERTIFICATE

Certified that the School building was inspected by me on 31.05/2024 and found to be fit/unfit to conduct classes for the period 2024 - 2025 for the reasons stated above.

Place : Palluruthy
Date : 31-05-2024




Asst. **SASIKALARA**
ASSISTANT ENGINEER
COCHIN MUNICIPAL CORPORATION